

SINE SOURCE ENGINEERING

95 W Golf Course Road, Suite 102, Logan, UT 84321

office: (435) 787-1445 . fax: 1-877-207-3199

www.sinesource.net

ADDENDUM

NIBLEY CITY
1200 WEST REDESIGN
DIVISIONS 26 AND 27
7/27/2023

1. Cobra heads at corners of roundabout were originally noted to be a base bid of fixtures installed to RMP standards with an alternate for owner furnished fixtures. The owner has determined that they will purchase/maintain these fixtures. Various revisions have been made to eliminate references to base/alternate bids and to remove RMP references and installations required by RMP. See sheets ES103, 5/ES501, ES502, EP601, and EP602
2. Clarification: Circuit serving future signage updated. See ES103
3. Clarification: Circuits for pedestrian flashers adjusted to show two home-runs and be consistent with panel schedule. See ES103
4. Detail 5/ES501 adjusted to eliminate incorrect references—and for RMP/cobra lighting as noted above.
5. Clarification: A lighting control relay panel was erroneously shown in the lighting control riser diagram. Schedule has been eliminated.
6. Pole base detail 1/ES502 and Pole Base/Rebar Layout detail 4/ES502 modified to be applicable to decorative fixtures and to cobra head poles as noted above
7. Pole base detail 1/ES502 modified to adjust rebar requirements at top of base.